



255 Diesel Road › St. Augustine, FL USA 32084  
904.829.0500 › FAX: 904.827.2156  
Sales Inquiry Hotline: 800.882.4343  
Customer Service Hotline: 800.248.2980  
[www.luhrs.com](http://www.luhrs.com) › [sales@luhrs.com](mailto:sales@luhrs.com)

## SERVICE BULLETIN

Contact: Mike Hankins, Director of Customer Relations  
Luhrs Corporation  
[mhankins@luhrs.com](mailto:mhankins@luhrs.com)

June 3, 2003

Models Affected: All 2003 and 2004 models

It has come to our attention that there is a possibility that some Luhrs vessels in recent months have not had the shifter stop screws adjusted correctly. Please take a moment and ensure that the levers just touch the stop screw at the end of its extreme travel. Approved labor for this inspection is 1 hour. Documentation of the units is required whether or not this stop screw is correct.

Questions can be communicated to Luhrs Engineering or Warranty/Service department.  
Thanks for your assistance.

Mike Hankins  
(904) 827-2025  
(800) 578-0852