



ALERT: #28-O-06-300-01

DATE: Oct. 27, 2006

SUBJECT: Sun shade supports

Model Affected: 28-Open Hull #BP101 thru #BP180

Time Allotted: 8.0 Hours

All boats in the affected serial number range should be modification performed

It has come to our attention that there is a possibility that the sun shades have shown signs of premature stress. Should this issue be reported the attached SOP should be followed to accomplish the repair.

All parts are needed for this modification will be sent to you.

Please contact Customer Service should you have any questions.

Thank you for your assistance.

Best regards,

A handwritten signature in red ink, appearing to read "Mike Hankins".

Mike Hankins
Director, Customer Service