



**EDITION: #GEN-07-008-01**  
**DATE: Jan. 8, 2007**

**SUBJECT: Potential failure of the Cummication(CANbus)  
Cable in the Engine Control.**

January 2, 2007

Model Affected: Luhrs 410 Open

There exists the possibility that during installation a severe bend may have been put in the Glendinning Marine Products EEC3 Engine Controls' CANbus "Communication Cable", specifically the cable connecting the engine room "Control Processor", and the main helm control station. This could cause engine control failure, and must be corrected as soon as possible.

A kit has been developed to solve issues and is readily available.

Please contact your local selling dealer to install this product.

Best regards,



Mike Hankins  
Director, Customer Service

