



255 Diesel Road › St. Augustine, FL USA 32084
904.829.0500 › FAX: 904.827.2156
Sales Inquiry Hotline: 800.882.4343
Customer Service Hotline: 800.248.2980
www.luhrs.com › sales@luhrs.com

SERVICE BULLETIN

Contact: Mike Hankins, Director of Customer Relations
Luhrs Corporation
mhankins@luhrs.com

November 21, 2002

Models Affected: All 2003 and previous models

Luhrs has discovered that the existing lazarette hatch may allow for some water infiltration into the lazarette. To improve the seal around the lazarette lid, Luhrs is providing gasket material to the selling dealers.

Please contact your selling dealer to install this product improvement, which will be processed pursuant to normal warranty conditions. Questions can be communicated to Luhrs Engineering or Warranty/Service department.
Thanks for your assistance.

Mike Hankins
(904) 827-2025
(800) 578-0852