



ALERT: GEN# 06-348-01

DATE: December 14, 2006

SUBJECT: *Organism growth in strainers, collection manifolds, and other seawater collecting components.*

TO: *All Luhrs Dealers*

FROM: *Luhrs Customer Service Department*

Please be observant, when servicing or winterization occurs, to verify whether any growth may be obstructing proper water exit. Customers should be notified by the dealer service department as part of ongoing communications with their customer that maintenance items like this are not covered under warranty..

MODEL(s) AFFECTED: ALL

Authorized Labor Time: NOT APPLICABLE

Any questions, or schedule issues, should be directed toward Luhrs Customer Service representatives.

Best regards,

A handwritten signature in purple ink, appearing to read "Mike Hankins".

Mike Hankins
Director, Customer Relations